

- A. CD24 C
- B. G00D
- THE 2L POSITION INDICATOR LAMP MALFUNCTIONED THRU-OUT
 THE 9R SIDE. WEAK IMAGES OF ADJACENT POSITION INDICATORS
 WERE IMAGED DURING EXPOSURE OF THE CORRECT POSITION
 INDICATORS THRU-OUT BOTH SIDES. CLOCK COUNTER FRAMES 134
 THRU 267 ARE DEGRADED ON BOTH SIDES DUE TO EXCESSIVE
 AIRCRAFT MANEUVERING. THE LAST 6 FEET OF THE 9R SIDE AND
 THE LAST 3 FEET OF THE 9L SIDE WERE SEVERELY SCRATCHED
 AND ABRAIDED AS FILM EXHAUSTION BECAME IMMINENT. 9L
 FILM CONTAINS 10 FRAMES MORE THAN THE 9R.

END OF MESSAGE